


Standard  
 spelatura cavetti  
 cordati, solidi e flessibili  
 stranded, solid and  
 flexible wires stripping




1


L = Fase/Phase  
 N = Neutro/Neutral  
 ⊕ = Terra/Earth




2




3




4





5




6



7





Standard

spelturacavetti cordati, solidi e flessibili stranded, solid and flexible wirestripping	<table border="1"> <tr><td>0,5-1-8-9</td></tr> <tr><td>1,5-2,5-9-10</td></tr> </table>	0,5-1-8-9	1,5-2,5-9-10
0,5-1-8-9			
1,5-2,5-9-10			

L   ⊕   N

L   ⊕   N


1

L = Fase/Phase  
N = Neutro/Neutral  
⊕ = Terra/Earth




2


H05RN-F 3G0.75



3




4




5

Sfilare il morsetto dal carter per cablaggio, re-inserire una volta collegato  
Slide off the terminal from the internal carter for cabling, then slide back in once finished



6



7

